



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

April 19, 2011

Reviewed: 

Mine Name: Ursa Major	Permit Number: S/055/0017
Operator Name: Land of Health, LLC	Inspection Date: April 19, 2011
Inspector(s): Sue Fivecoat BLM and Wayne Western DOGM	Time: 9:40 – 10:00 AM
Other Participants:	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond amount is \$1,000 and the permit area is 5 acres. The permit fees are current for 2010.

The Operator should reduce the permit area and/or increase the bond.

The amount of disturbance was minimal. The pits in the pictures from the previous inspection were filled in. In the 2010 annual report the Operator reported that the area was reclaimed and that no material was removed.

Directions:

On State Highway 24 go 0.5 miles west of mile marker 105, sign 6650 East if you get to Swing Arm ATV area then you have gone too far. Go north for 0.2 miles, T intersection and then turn south and then wing east at 0.5 miles from SR 24 go through a notch and then 0.1 miles more – if you start going up hill then you have gone too far. Hike north for 100 yards.

Conclusions and Recommendations:

The Division should request that the Operator increase the bond amount. The permit area could be reduced to one acre.


Inspector's Signature

WHW

cc: (OPERATOR)

Sue_Fivecoat@blm.gov

O:\M055-Wayne\S0550017-Ursa Major\Inspections\ins121302attum.doc



Notch that one must drive through to get to site, going east.



Mine is located behind the hill – Factory Butte is on left top part of photo



Mined area.



Mined area